

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.:	6,871,788 B2	Issued:	March 29, 2005
Serial No.:	09/936,935	Examiner:	Karl D. Frech
Inventors:	Tompkin et al.	Art Unit:	2876
Filed:	January 31, 2002	Docket No.:	1093-36PCT/US
Confirm. No.:	3010	Dated:	April 13, 2005
For:	COIN WITH DIFFRACTION STRUCTURE		

Mail Stop Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

I hereby certify this correspondence is being deposited with the United States Postal Service as first class mail, postpaid in an envelope, addressed to: Mail Stop Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on April 13, 2005.

Signature: _____

**REQUEST FOR CERTIFICATE OF CORRECTION
OF PATENT UNDER 37 C.F.R. § 1.322(a) and §1.323**

Sir:

Upon receipt and review of the above-identified issued patent, errors on the part of the Patent Office. These errors are set forth as follows:

IN THE SPECIFICATION:

Column 7, line 28, now reads: "detector 22a associated with the coin **la** of the first kind of"
should read: "detector 22a associated with the coin **1a** of the first kind of"

Column 17, line 43, now reads: "passage, that a chord of the **corn** which is 1.5 mm wide"
should read: "passage, that a chord of the **coin** which is 1.5 mm wide"


Patent No.: 6,871,788 B2
Application Serial No.: 09/936,935
Request for Certificate of Correction

Docket No.: 1093-36PCT/US

The errors were not caused by the Applicants and, therefore, no fee is due.

Form PTO-1050 is attached hereto in duplicate with at least one copy being suitable for printing.

Respectfully submitted,

A handwritten signature in black ink, reading "Kevin E. McDermott", written over a horizontal line.

Kevin E. McDermott
Registration No.: 35,946
Attorney for Applicants

HOFFMANN & BARON, LLP
6900 Jericho Turnpike
Syosset, New York 11791
(516) 822-3550
KEM:mf
203333_1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,871,788 B2
DATED : March 29, 2005
INVENTOR(S) : Tompkin et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

IN THE SPECIFICATION:

Column 7, line 28, now reads: “detector 22a associated with the coin **la** of the first kind of”
should read: “detector 22a associated with the coin **1a** of the first kind of”

Column 17, line 43, now reads: “passage, that a chord of the **corn** which is 1.5 mm wide”
should read: “passage, that a chord of the **coin** which is 1.5 mm wide”

MAILING ADDRESS OF SENDER

PATENT NO. 6,871,788 B2

Kevin E. McDermott, Esq.
HOFFMANN & BARON, LLP
6900 Jericho Turnpike
Syosset, New York 11791